

GM CUSTOMER CARE AND AFTERSALES  
DCS3195  
URGENT - DISTRIBUTE IMMEDIATELY

Date: June 26, 2014

Subject: 14294A – Safety Recall  
Ignition Key  
Revised Part Information Section

Models: 2010-14 Chevrolet Camaro

To: All Chevrolet Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and  
Service Director, Parts Manager, New Vehicle Sales Manager,  
Used Vehicle Sales Manager, and Warranty Administrator

The bulletin has been revised to include part number information and add a declination process, if the customer refuses this recall repair. Please discard all copies of bulletin 14294.

END OF MESSAGE  
GM CUSTOMER CARE AND AFTERSALES